

SERVICE BULLETIN

BULLETIN NUMBER: SB-0022
REVISION: 1-0-0
DATE: SEPT 2005

PRODUCT DESCRIPTION: All MT-4 TX's

DE REFERENCE / ECO: CO 6096 & 6097

PRODUCTS EFFECTED:	Model Number	Model Number
	UT-4D420-B0-X00	UT-4B420-00-X00
	UT-4D420-B1-X00	UT-4B420-01-X00
	UT-4D420-R0-X00	UT-4R420-00-X00
	UT-4D460-B0-X00	UT-4B460-00-X00
	UT-4D460-B1-X00	UT-4B460-01-X00
	UT-4D460-R0-X00	UT-4R460-00-X00
	VT-4D140-B0-X00	VT-4B140-00-X00
	VT-4D140-B1-X00	VT-4B140-01-X00
	VT-4D140-R0-X00	VT-4R140-00-X00
	VT-4D160-B0-X00	VT-4B160-00-X00
	VT-4D160-B1-X00	VT-4B160-01-X00
	VT-4D160-R0-X00	VT-4R160-00-X00

SYMPTOMS: Fails to generate test pattern for testing C4FM Modulation Fidelity

CAUSE: Problem with RSS in service mode after adjusting reference oscillator.

SOLUTION: Exit "Service Mode" after adjusting reference oscillator and then re-enter "Service Mode" before activating the test pattern for testing C4FM Modulation Fidelity.

RETURN REQUESTS: Please contact the service department for obtain an RMA number and shipping instructions at 1-800-664-4066 or service@danelec.com

REVISION HISTORY:	Rev	Date	Description
	1-0-0	09/26/2005	First Release